

**App. A:
Bolcome Decl., Ex. 8.i
Part IV**

RD-6542-1 Rev. 2-15-61

.I.	GUN EXAMINATION REPORT NUMBER:	MODEL: 70
GENERAL CONDITION:	GOOD	R #: 6319824
OUTSIDE WORK:	NO	DATE: 3-1-71
FIRED AMMO TYPE:	—	FROM: GLOBE #10 TUCSON, ARIZONA
& CONDITION:	—	GUN #: 6319824
PROOF: R.E.P. - E	INSP.: 58	CODE: AT = 3/70
HEADING: O.K.	—	GA./CAL.: 270 WIN.
BREECH OPENING:	—	CHECKED BY: C. Prentiss
RECOIL SHOULDERS:	—	APPROVED: _____
CHAMBER: O.K.	—	APPROVED: _____
TEST: NO	—	APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style)	—	APPROVED: _____

~~NO COMPONENT DAMAGED OR BROKEN. TRIGGER CONNECTOR
SEAR ENGAGEMENT = .005 (MIN. 15.015)~~

COMPLAINT: FIRES ON CLOSING BOLT

INCIDENT: FOLLOW DOWN

COMMENTS: THE TRIGGER CONNECTOR - SEAR ENGAGEMENT IS
NOT ENOUGH FOR PROPER SUPPORT, ALLOWING THE
FIRING PIN TO FOLLOW DOWN.

PLAINTIFF'S
EXHIBIT

3280

AL 0029812

10f1

EXHIBIT 35
PAGE 55

RD-5542-1 Rev. 2-15-61

P.I. ND GUN EXAMINATION REPORT NUMBER: 700

GENERAL CONDITION: GOOD

OUTSIDE WORK: NO

MODEL: 700

R #: 03978

DATE: 3-1-71

FROM: ERBACHERS SPESCHUTZ

MADISON, OHIO

FIRED AMMO TYPE: -

GUN #: 278328

& CONDITION: -

CODE: CD - 4/37

PROOF: R.E.P. INSPECTION: D TEST: 87

GA./CAL.: 7MM MAG.

HEADING: O.K.

CHECKED BY: C.P

BREECH OPENING: -

APPROVED: -

RECOIL SHOULDERS: O.K.

APPROVED: -

CHAMBER: O.K.

APPROVED: -

TEST: NO

APPROVED: -

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: -

NO COMPONENT DAMAGE OR BREAKAGE.

COMPLAINT: "FIRRED TWO TIMES WHEN CLOSING BOLT."

INCIDENT: FOLLOW DOWN

PLAINTIFF'S
EXHIBIT
3281

COMMENTS: TRIGGER CONNECTOR-SEAR ENGAGEMENT .025. THE

TRIGGER ETC. WAS FOUND TO BE COATED WITH A HEAVY-

GREASE-LIKE LUBRICANT WHICH WOULD CAUSE TRIGGER

RETRACTION TO BE ERRATIC. THIS APPARENTLY HAPPENED

TO THE CUSTOMER - TRIGGER DID NOT RETRACT AND

WHEN THE BOLT WAS CLOSED THE FIRING PIN

FOLLOWED DOWN.

1 of 1

AL 0029813

EXHIBIT 35
PAGE 56

RD-6542-1 Rev. 2-15-61

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
GENERAL CONDITION: GOOD R #: 01780
OUTSIDE WORK: SCOPE MOUNTED, REAR SIGHT DATE: 1-26-71
LEAF REMOVED. FROM: GREEN BROOK SOC. INC.
FIRED AMMO TYPE: GREEN BROOK, N.J.
& CONDITION: ASSEMBLED P
PROOF: R.E.P.-E INSPI.: 74 TEST: 87 GUN #: 6362025
HEADING: O.K. CODE: WT = 8/70
BREECH OPENING: CHECKED BY: C. PROSSER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: NO APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style)
COMPONENTS O.K. APPROVED: _____

COMPLAINT: "UPON RELEASING THE SAFETY MAY FIRE"

INCIDENT: FOLLOW DOWN

PLAINTIFF'S
EXHIBIT

3282

COMMENTS: THE MALFUNCTION CAN NOT BE DUPLICATED.
HOWEVER, THE SEAR-CONNECTOR ENGAGEMENT IS NOT
TO SPECIFICATION (.008 SHOULD BE .015 MIN.) THIS COUPLED
WITH ANY TRIGGER BIND, SUCH AS TOO HEAVY LUBRICANT,
MIGHT CAUSE A MALFUNCTION. ENGAGEMENT
CORRECTED.

1 of 1

AL 0029814

AD-55-A-1 Rev. 2-15-61

GUN EXAMINATION REPORT NUMBER: 700

GENERAL CONDITION: NEW

MODEL: 700

OUTSIDE WORK: FRONT TRIM - ADJUSTED

R#: 29996

SERIAL NO: RE-ADJUSTED.

DATE: 1-4-71

FIRED AMMO TYPE: -

PROD: LEFAVOUR'S SKIS

& CONDITION: ASSEMBLED

WILMINGTON, NC

PROP: P.E.P.F INSPI: 0 TEST: 98

GUN #: 3289151

HEADING: O.K.

CODE: DT = 9170

BREECH OPENING: -

GA./CAL.: 300S

RECOIL SHOULDERS: O.K.

CHECKED BY: C. PROESLER

CHAMBER: O.K.

APPROVED:

TEST: N/C.

APPROVED:

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED:

- NO DAMAGED OR BROKEN PARTS.

COMPLAINT: "SEVERAL TIMES GUN WENT OFF WHEN CLOSING BOLT."

INCIDENT: FOLLOWS DOWN

COMMENTS: SEAR - TENSER CONNECTOR ENGAGEMENT .005,

MINIMUM IS .015. THIS LETS THE SEAR SLIP OFF THE

CONNECTOR UNDER PRESSURE AND FALLON DOWN

RESULTS.

PLAINTIFF'S
EXHIBIT

3288

1 of 1

AL 0029815

EXHIBIT 35
PAGE 58

Castellan Corp.

P.I. No

GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDLGENERAL CONDITION: USED - GOODR #: 00931OUTSIDE WORK: SCOPE MOUNTEDDATE: 1-12-71FROM: JOHN M. ANGELOFIRED AMMO TYPE: -LANSING, MICH.

& CONDITION:

ASSEMBLER C

PROOF: R.E.P.INSP.: BTEST: 87GUN #: 247248CODE: EN = 10/66HEADING: O.K.GR./CAL.: 300G SPR.BREECH OPENING: -CHECKED BY: C. PROSSERRECOIL SHOULDER: O.K.

APPROVED: _____

CHAMBER: O.K.

APPROVED: _____

TEST: NO

APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: _____

NO BROKEN COMPONENTS.COMPLAINT: FIRE AS BOLT WAS PULLED HALF WAY UP.

**PLAINTIFF'S
EXHIBIT**
3284

INCIDENT: APPARENTLY TRIGGER FAILED TO RETRACT.COMMENTS: TRIGGER-CONNECTOR-SEAR ENGAGEMENT .020,NO INTERFERANCE INDICATED AND MALFUNCTION NOTDUPLICATED. SOME EVIDENCE OF TOO HEAVY ALUBRICANT BEEN USED. SUGGEST CLEANING ANDINFORMING CUSTOMER HE SHOULD USE VERY LIGHT
OR NO LUBRICANT.

AL 0029816

1 of 1

A Rev. 7-27-71	<i>Customer Complaint</i>	
ITEM:	ITEM IDENTIFICATION NUMBER:	MODEL: 750-501
INTERNAL CONDITION:	REF. NO.: 750-501	
OUTSIDE DRA: TWO	DATE: 7-2-71-72	
FIREARM TYPE: RIFLE		
E CONDITION: GOOD		
PROOF: ✓	INSP.: ✓	TEST: ✓
HEADING: ✓		
BREACH OPENING: ✓		
RECOIL SHOULDERS: ✓		
CHAMBER: ✓		
TEST: ✓		
COMPONENT CONDITION: (Damaged, Broken, Old Style)		
K		
S		
COMPLAINT: "BULLET STICKS IN CHAMBER ALSO BOLT IS IMMOVABLE FOR SOME REASON."		
INCIDENT:		
PLAINTIFF'S EXHIBIT 3286		

**PLAINTIFF'S
EXHIBIT**

3286

COMMENTS: THE CUSTOMER PULLED THE BULLET OUT OF THE
CASE LEAVING IT IN THE THROAT. THIS APPARENTLY
IS AN AMMUNITION PROBLEM (PER M. WALKER).

THE BOLT CATCHING IS CAUSED BY PUSING THE
SAFETY ON BEFORE LOCKING THE BOLT THUS CATCH-
ING THE SAFETY AND IN THE COCKING CAM.

- 10f -

AL(X)29819

RD-6542- Rev. 2-15-61

P.I. No GUN EXAMINATION REPORT NUMBER: 700 BDL
GENERAL CONDITION: NEW R #: 23406
OUTSIDE WORK: No DATE: 11-2-70

FIRED AMMO TYPE: - FROM: OCONTO, WIS.
& CONDITION: - GUN #: 6248578
PROOF: - INSP.: - TEST: - CODE: PS = 6/69
HEADING: - CAL/CAL.: 7MM
BREECH OPENING: - CHECKED BY: C. PROSSER
RECOIL SHOULDERS: - APPROVED: -
CHAMBER: - APPROVED: -
TEST: No APPROVED: -
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: -
TRIGGER CONNECTOR BROKEN.

COMPLAINT: FIRE WHEN SAFE IS REMOVED & WON'T COCK
AT TIMES.

INCIDENT: -

COMMENTS: MALFUNCTION WAS CAUSED BY THE BROKEN
TRIGGER CONNECTOR.

PLAINTIFF'S
EXHIBIT
3287

1 of 1

AL 0029820

EXHIBIT 35
PAGE 61

ME-65-A-1 Rev. 2-15-61

Cecilian Complaint

P.I.	GUN EXAMINATION REPORT NUMBER:	MODEL: 760 121
GENERAL CONDITION: NEW	R #:	225-172
OUTSIDE WORK: NO	DATE:	11-7-70
Fired AMMO TYPE: -	FROM:	SHAW HORN
& CONDITIONS:	F. L. MERRILL	
PROOF: P.S.P. INSP.: 14 TEST: F. L. MERRILL	GUN #: 6311234	
HEADING: O.K.	CODE: BT = 170	GRADE/CAL.: 30-06
BREACH OPENING: -	CHECKED BY: C. PROESLER	APPROVED: _____
RECOIL SHOULDERS: O.K.	APPROVED: _____	APPROVED: _____
CHAMBER: -	APPROVED: _____	APPROVED: _____
TEST: ✓	APPROVED: _____	APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style)	APPROVED: _____	APPROVED: _____

COMPLAINT: EVERY TIME YOU PUSH THE ROD UPON THE
RIFLE FIRE.

INCIDENT: FOLLOWED DOWN

COMMENTS: THE ENGAGEMENT OF THE SEAR, TRIGGER CON-
NECTOR SET TOO CLOSE AT FINCH ASSEMBLY. (GOOSED)



10f

AL 0029821

EXHIBIT 35
PAGE 62

RD-554A-1 Rev. 2-15-61

Customer Complaints

1. NO

GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADL

GENERAL CONDITION: NEW

R #: 26143

OUTSIDE WORK: NO

DATE: 11-12-70

FIRED AMMO TYPE: -

FROM: DARIN SEPT. L.C. Co.

& CONDITION: -

BANGOR, MAINE

PROOF: R.E.P. INSP.: -

ASSEMBLER 41

GUN #: 6219140

HEADING: O.K.

CODE: L5 = 2/69

BREECH OPENING: -

GAT./CAL.: 300 G

RECOIL SHOULDER: -

CHECKED BY: C. PROSSER

CHAMBER: O.K.

APPROVED: _____

TEST: NO

APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: _____

TRIGGER CONNECTOR BROKEN.

APPROVED: _____

COMPLAINT: "WILL NOT STAY COCKED"

INCIDENT: FOLLOWS DOWN

COMMENTS: THE BROKEN CONNECTOR MAKES RETRACTION
UNDER SEAR UNCONTROLLABLE. THE CONNECTOR
FAILING TO RETRACT CAUSES FOLLOW DOWN.

PLAINTIFF'S
EXHIBIT

3289

1 of 1

AL 0029822

EXHIBIT 35
PAGE 63

RD-6542-1 Rev. 2-15-61

Customer Complaint

P.I. <u>A.D.</u>	GUN EXAMINATION REPORT NUMBER:	<u>700 BDL</u>	
GENERAL CONDITION:	<u>NEW</u>	R # : <u>26910</u>	
OUTSIDE WORK:	<u>NO</u>	DATE: <u>11-17-70</u>	
FIRED AMMO. TYPE:	<u>-</u>	FROM: <u>GOLD BUSH SALES</u>	
& CONDITION:		<u>BROOKLYN, N.Y.</u>	
PROOF: <u>R.E.P.</u>	INSP.: <u>74</u>	ASSEMBLER #30 TEST: <u>79</u>	GUN #: <u>G288540</u>
HEADING: <u>O.K.</u>			CODE: <u>C5 = 4/69</u>
BREECH OPENING: <u>-</u>			G.A./CAL.: <u>3006</u>
RECOIL SHOULDERS: <u>O.K.</u>			CHECKED BY: <u>C. PROSSER</u>
CHAMBER: <u>O.K.</u>			APPROVED: _____
TEST: <u>NO</u>		X	APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style)		X	APPROVED: _____
			APPROVED: _____

COMPLAINT: FIRED UPON CLOSING BOLT.

INCIDENT: APPARENTLY FOLLOWED DOWN.

COMMENTS: ENGAGEMENT O.K. NO REASON FOR MALFUNCTION COULD BE FOUND. THE MALFUNCTION COULD NOT BE REPRODUCED.



1 of 1

AL 0029873

Customer Complaint

GUN NUMBER:	DATE:		
SERIAL NUMBER:	R#:		
CHASSIS NUMBER:	ENTER:		
FIRING MODE:	FROM:		
& CONDITION:	GUN #:		
PROOF:	INSP.:	TEST:	CODE:
HEADING:			EX./CAL.:
BREECH OPENING:			CHECKED BY:
RECOIL SHOULDER:			APPROVED:
CHAMBER:			APPROVED:
TEST:			APPROVED:
COMPONENT CONDITION: (Damaged, Broken, Old Style)			APPROVED:

No PROOF OR DEFECTIVE COMPONENTS.

COMPLAINT: GUN FIRES WHEN BOLT IS CLOSED.

INCIDENT: FOLLOWS DOWN

COMMENTS: THE SEAR-CONNECTOR ENGAGEMENT WAS SET TOO CLOSE BY FINAL ASSEMBLY.

PLAINTIFF'S
EXHIBIT
3291

1 of 1

AL 0029824

EXHIBIT 35
PAGE 65

RD-65/2-1 Rev. 2-15-61

Plaintiff's Complaint.

P.I.

GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL.

GENERAL CONDITION: GOOD

R #: 27632

OUTSIDE WORK: STOCK BEDDING ALTERED.

DATE: 12-3-70

SCOPE MOUNTED.

FROM: R. ROYSE

FIRED AMMO TYPE: _____ PORTLAND, OREGON

& CONDITION: ASSEMBLER GO

GUN #: 6275235

PROOF: R.E.P. INSPI.: 9 TEST: .55 CODE: ES = 10/69

GRA./CAL.: 7MM REV. V.A.

HEADING: O.K.

CHECKED BY: C. PROSSER

BRECH OPENING: _____ APPROVED: _____

RECOIL SHOULDERS: O.K. APPROVED: _____

CHAMBER: O.K. APPROVED: _____

TEST: No APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

COMPLAINT: POOR GROUPS, FIRED WHEN SAFETY WAS PUSHED TO FIRE POSITION.

INCIDENT: BARREL BORE ROUGH, FOLLOWED DOWN.

COMMENTS: THE FOLLOWING DOWN CAN NOT BE DUPLICATED.

BARREL BORE EXCESSIVELY ROUGH - SHOULD BE REPLACED.

PLAINTIFF'S
EXHIBIT

3292

1 of 1

AL 0029825

EXHIBIT 35
PAGE 66

AP-1 Rev. 2-15-61

Customer Complaint

P.I. NO

GUN EXAMINATION REPORT NUMBER:

MODEL: 700 BDL

GENERAL CONDITION: NEW

R #: 27297

OUTSIDE WORK: NO

DATE: 11-23-70

FIRED AMMO TYPE: -

VERNAL, UTAH

& CONDITION

PROOF: R.E.P. 2 INSP: 74 TEST: 55 ASSEMBLER: 13

GUN #: 6296977

HEADING: -

CODE: LT = 2/70

BREECH OPENING: -

GA./CAL.: 300G

RECOIL SHOULDERS: -

CHECKED BY: C. PROSSER

CHAMBER: -

APPROVED: _____

TEST: NO

APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: _____

TRIGGER CONNECTOR CLEARANCE - .003 OUTSIDE MODEL

DRAWING: CONNECTOR TOGGLE CLEARANCE = .005 OUTSIDE

MODEL DRAWING. THIS ADDS UP TO .009 MORE MOVE-
MENT UP, OF CONNECTOR THAN THERE SHOULD BE TO
POTENTIAL INTERFERENCE WITH THE GEAR.

COMPLAINT: "TRIGGER FIRES SOMETIMES WHEN TAKEN OFF
SAFETY." (EXTRACTOR FAULTY)

INCIDENT: FOLLOWS DOWN WHEN SAFE IS PUSHED OFF.

COMMENTS: THE FOLLOWING DOWN MALFUNCTION COULD NOT
BE VERIFIED ALTHOUGH EXCESSIVE CONNECTOR
Movement IS PRESENT.

EXTRACTOR CLAW DAMAGED.

PLAINTIFF'S
EXHIBIT

3293

1 of 1

AL 0029826

*Complaint*P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700GENERAL CONDITION: NEW R #: 27774OUTSIDE WORK: NO DATE: 12-10-70FIRED AMMO TYPE: - FROM: KOEGERE FARMS
SUPPLY& CONDITION: - DURANGO, CO.PROOF: R.E.P.A INSP.: 318 TEST: 13 GUN #: 6367225HEADING: - CODE: DT = 9/70BREECH OPENING: - S.K./CAL.: 3006RECOIL SHOULDERS: - CHECKED BY: C. PROSSERCHAMBER: - APPROVED: _____TEST: NO APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

COMPONENTS O.K.

COMPLAINT: "HAMMER IN BOLT WILL NOT STAY COCKED."INCIDENT: FOLLOWS DOWN.COMMENTS: SEAR, TRIGGER CONNECTOR, ENGAGEMENT
ADJUSTED TOO CLOSE (.005) MINIMUM IS .015, THIS
LETS THE SEAR SLIP OFF THE CONNECTOR UNDER
PRESSURE OF FIRING PIN FOLLOWS DOWN.

RE-ADJUSTED ENGAGEMENT.

1 of 1

PLAINTIFF'S
EXHIBIT

3294

AL 0029827

Customer Complaint

P.I. NOGUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 EDLGENERAL CONDITION: GOODR #: 29327OUTSIDE WORK: EXTRACTOR RING - GROUND OFF.DATE: 12-15-70TRIGGER ADJUSTED - EXTRACTOR SCREEN
APPEARS UNTOUCHED.FROM: HARPER F-T, INC.
WILLIAMSPORT, PA.FIRED AMMO TYPE: -GUN #: 626-2773PROOF: R.E.F.E INSPI.: 17 TEST: 55CODE: WS = 2/10MATING: -L.H./R.H.: -BREECH OPENING: -CHECKED BY: C. PROSSERRECOIL SHOULDERS: O.K.

APPROVED: _____

CHAMBER: O.K.

APPROVED: _____

TEST: No

APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: _____

NO DEFECTIVE OR BROKEN COMPONENTS.COMPLAINT: "FIRED UPON CLOSING"INCIDENT: FOLLOWED DOWNCOMMENTS: SEAD - CONNECTOR ENGAGEMENT .003, MINIMUM IS .015,
THIS LETS THE SEAD SLIP OFF THE CONNECTOR UNDER
PRESSURE AND FOLLOW DOWN RESULTS.PLAINTIFF'S
EXHIBIT
3295

1 of 1

AL 0029828

PG-5740-1 Rev. 2-15-61

P.I. NO

GUN EXAMINATION REPORT NUMBER: 700 EDL

MODEL: 700 EDL

GENERAL CONDITION: NEW

R# : 29277

OUTSIDE WORK: NO

DATE: 12-21-70

FIRED AMMO TYPE: -

FOR WEAPONS TEST

& CONDITION: -

GUN #: 333-4752

PROOF: Q.F.P. INSPI.: - TEST: 49 CODE: WT = 5/70

HEADING: O.K.

GA./CAL.: 270 WIN.

BREACH OPENING: -

CHECKED BY: G. FRASER

RECOIL SHOULDERS: O.K.

APPROVED: -

CHAMBER: O.K.

APPROVED: -

TEST: NO

APPROVED: -

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: -

SAFETY CAM BROKEN OFF OF SEAR.

COMPLAINT: SAFETY DOES NOT WORK

INCIDENT: FIRE'S WITH SAFETY ON

COMMENTS: SAFETY CAN NOT FUNCTION WITHOUT THE CAM

ON THE SEAR-SAFETY CAM.

PLAINTIFF'S
EXHIBIT

3296

10f1

AL 0029829

EXHIBIT 35
PAGE 70

AL-67-A-1 Rev. 2-15-61

P.I.	GUN IDENTIFICATION REPORT NUMBER:	MODEL:	700 324
GENERAL CONDITION:	Good	R #:	2372
OUTSIDE WORK:	No	DATE:	12-21-70
FIRED AMMO TYPE:		FROM:	PL. A. 24 C.
& CONDITION:		DEPARTMENT:	DEPT. OF DEFENSE
PROOF:	PERF.	INSP.:	TEST: ✓
HEADING:	O.K.	GUN #:	2372
BREACH OPENING:		CODE:	P.R. = 1/13
RECOIL SHOULDERS:	O.K.	GR./CAL.:	30 MM. M61
CHAMBER:	O.K.	CHECKED BY:	S. PROSEK
TEST:	No	APPROVED:	
COMPONENT CONDITION:	(Damaged, Broken, Old Style)	APPROVED:	
		APPROVED:	
		APPROVED:	

COMPLAINT: "GUN FIRED WHEN PICKED UP"

INCIDENT: FOLLOWING ENGAGEMENT

COMMENTS: TRIGGER CONNECTOR - SEEN ENGAGEMENT .010
MIN. ENGAGEMENT = .015. MALFUNCTION NOT DUPLICATED.
ENGAGEMENT RE-ADJUSTED.

PLAINTIFF'S
EXHIBIT

3297

10f1

AL 0029830

EXHIBIT 35
PAGE 71

RD-6542-1 Rev. 2-15-61

Customer Complaint

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADL

GENERAL CONDITION: NEW R #: 00285

OUTSIDE WORK: NO DATE: 1-6-71

FIRED AMMO TYPE: - FROM: KMART SP-6, Dec

& CONDITION: ASSEMBLER 12 ST. CLAIR SHORES, MICH

PROOF: R.E.P. INSP.: - GUN #: 6248840

HEADING: O.K. TEST: - CODE: P.S. = 6/69

BREECH OPENING: - OK./CAL.: 7MM REM.

RECOIL SHOULDERS: O.K. CHECKED BY: C. PROSSER

CHAMBER: O.K. APPROVED: -

TEST: NO APPROVED: -

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: -

BROKEN TRIGGER CONNECTOR

COMPLAINT: DEFECTIVE

INCIDENT: FOLLOWS DOWN

COMMENTS: THE BROKEN TRIGGER CONNECTOR FAILS TO
RETRACT TO SUPPORT THE SEAR IN COCKED POSITION.
WITHOUT SUPPORT, THE SEAR FOLLOWS DOWN.

PLAINTIFF'S
EXHIBIT

3298

AL 0029831

EXHIBIT 35
PAGE 72

RD-6542-1 Rev. 2-15-61

Customer Complaint

P.I. NoGUN EXAMINATION REPORT NUMBER: _____ MODEL: 700GENERAL CONDITION: USEDR #: 00598OUTSIDE WORK: NODATE: 1-11-71FIRED AMMO TYPE: -FROM: REM. ARMS OF CAN.
TORONTO, ONT., CANADA& CONDITION: -GUN #: 621 G023PROOF: P.E.P.ASSEMBLER # 64INSPI. UTEST: 55CODE: L5=2/69HEADING: -SR./CAL.: .350 REM. MAG.BREECH OPENING: -

CHECKED BY: _____

RECOIL SHOULDERS: -

APPROVED: _____

CHAMBER: O.K.

APPROVED: _____

TEST: No

APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: _____

NO BROKEN COMPONENTS.COMPLAINT: SEAR WILL NOT HOLD.INCIDENT: FOLLOW DOWN.COMMENTS: SEAR-TRIGGER CONNECTOR ENGAGEMENT OK;IMAL-
FUNCTION COULD NOT BE DUPLICATED, HOWEVER BRIGH-
EDGE ON TRIGGER (TOP) INDICATES A SLIGHT INTERFER-
ENCE WHICH MAY HAVE CAUSED THE MALFUNCTION.PLAINTIFF'S
EXHIBIT

3299

1 of 1

AL 0029832

11/76 File Crimel

GUN EXAMINATION REPORT NUMBER: MODEL: 700 PDLGENERAL CONDITION: GOOD R #: 22750OUTSIDE WORK: NO TRIGGER ADJUSTMENT DATE: 10-16-70SCREW UNSEALED, POSITIONING CHANGED, FROM: CENTRALIA,FIRED AMMO TYPE: GUN #: 193-7& CONDITION: CODE: W13-5170PROOF: P.E.P. INSPI.: 7 TEST: CAL./CAL.: 222HEADING: CHECKED BY: C. PROSPERBREECH OPENING: APPROVED: RECOIL SHOULDER: APPROVED: CHAMBER: APPROVED: TEST: APPROVED: COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: OLD STYLE SCREW SAFETY CABLE ATTACHED ON SIDETRIGGER CONNECTOR BROKEN.COMPLAINT: FOLLOWS DOWN.INCIDENT: COMMENTS: FOLLOW DOWN WAS CAUSED BY THE BROKEN CONNECTOR.10/1
AL 0029841

RD-6542-1 Rev. 2-15-61

NO GUN EXAMINATION REPORT NUMBER: 700 MODEL: 700

GENERAL CONDITION: NEW R#: 22775

OUTSIDE WORK: No DATE: 10-15-70

FIRED AMMO TYPE: PA.

& CONDITION: GUN #: 6262918

PROOF: R.E.P. INSP.: 9 TEST: CODE: OS = 7/69

HEADING: O.K. GA./CAL.: 22-250

BREECH OPENING: CHECKED BY: C. PROSSER

RECOIL SHOULDERS: APPROVED:

CHAMBER: APPROVED:

TEST: FUNCTION ONLY APPROVED:

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED:

COMPLAINT: FOLLOWS DOWN WHEN SAFETY IS PUSHED OFF.

INCIDENT:

COMMENTS: THE DIMENSION FROM THE TOP OF THE TRIGGER TO
CENTER OF TRIGGER PIN HOLE BEING .011 OVERSIZE
ELIMINATES MOST OF THE CLEARANCE NEEDED FOR THE
TRIGGER-CONNECTOR TO RETRACT WITH THE SAFETY ON



101
AL 0029842

EXHIBIT 35
PAGE 75

RD-6542-1 Rev. 2-15-61

P - No GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADL

GENERAL CONDITION: NEW R #: 22730

OUTSIDE WORK: No DATE: 10-16-70

FIRED AMMO TYPE: _____ FROM: LIVONIA, MICH.

& CONDITION: GUN #: 6278113

PROOF: R.E.P. INSP: TEST: CODE: _____

HEADING: _____ PK./CAL.: 3006

BRECH OPENING: _____ CHECKED BY: C. PROSSER

RECOIL SHOULDER: _____ APPROVED: _____

CHAMBER: _____ APPROVED: _____

TEST: FUNCTION ONLY APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

CONNECTOR IS .005 UNDERSIZE ON .0080 DIMENSION (TRIGGER
CLEARANCE).

COMPLAINT: FOLLOWS DOWN

INCIDENT: _____

COMMENTS: CONNECTOR BEING TIGHT ON TRIGGER DID NOT RETRACT,
ACTION WOULD NOT COCK. AS LONG AS THE CONNECTOR
STAYED IN POSITION ON THE TRIGGER THE RIFLE WOULD
WORK O.K.



181
AL 0029843

EXHIBIT 35
PAGE 76

RD-6542-1 Rev. 2-15-61

P.T. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700

GENERAL CONDITION: GOOD R #: 21196

OUTSIDE WORK: SCOPE MOUNTED DATE: 10-2-70

FIRED AMMO TYPE: _____ FROM: DAVISON,
MICHIGAN.

& CONDITION: _____ GUN #: 6216922

PROOF: R.E.P. INSP.: 9 TEST: 87 CODE: L5 = 2/69

HEADING: O.K. GA./CAL.: 243 WIN.

BREECH OPENING: _____ CHECKED BY: _____

RECOIL SHOULDER: _____ APPROVED: _____

CHAMBER: O.K. APPROVED: _____

TEST: NO APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

TRIGGER CONNECTOR BROKEN.

COMPLAINT: FIRING PIN FOLLOWS DOWN

INCIDENT: _____

COMMENTS: THE CONNECTOR BEING BROKEN, ENGAGEMENT

BETWEEN IT AND THE SEAR WAS UNLIKELY THEREFORE
THE FIRING PIN WAS FREE TO FOLLOW DOWN.



EXHIBIT 35
PAGE 77